

9.6 CAL ARC SHIRT





DW-ARC9.6-S

Description

The Dromex[®] Arc product range is designed to protect the user from the hazards of heat and to reduce total burn injury when working in environments exposed to electric Arc hazards.

Dromex[®] Arc garments are manufactured with our exclusive Dromex[®] A.P.T[™] (Arc Protective Technologies) fabric blend, which has been carefully developed by our team along with industry experts and professionals to ensure specialised Arc safety and global standards are met. Our Dromex[®] A.P.T[™] fabric and garments have been tested to NFPA, ASTM, EN, SABS and IEC standards.

This shirt consists of the following:

- Silver flame retardant reflective tape on sleeves for enhanced visibility.
 Flame retardant melamine button closure front and sleeve plackets designed for ease of putting on and taking off.
- Seams with triple needle topstitching for added durability.
- Two chest pockets with a mitred flap and button closure.
- Sleeve cuffs with flame retardant melamine buttons.
- Left chest pocket with Dromex[®] Arc sidewinder.

 Right chest above pocket with ATPV 9.6 cal/cm² embroidery for garment suitability identification.

These garments are commonly used in the following industries:

- Automotive
- Construction
- Mining
- Petroleum
- Utilities and Power Generators
- Data centres
- High volume manufacturing
- Substations and switchrooms

Dromex[®] A.P.T[™] fabrics are self-extinguishing, heat resistant and resistant to ignition. Dromex[®] Arc garments are sewn with inherent flame retardant thread.

Special Instructions

Note: For electric Arc exposures, wear the correct number of flame resistant clothing layers as dictated by an electric Arc hazard analyst.

In potentially explosive environments, proper grounding procedures must be used for protection against electrostatic spark ignition.

Do not put on or remove garments when in a potentially explosive environment.

None of the materials or processes used in the manufacture of these products are known to be harmful to the wearer.

The manufacturer has examined under the system for ensuring quality of production by means of monitoring and inspection.

These Arc flash shirts are designed to accommodate the basic safety requirements and standards for Personal Protective Equipment. The information contained herein is intended to assist the wearer in the

selection of Personal Protective Equipment.

Actual conditions of use cannot be directly simulated in a test environment therefore it is the responsibility of the end user and not the manufacturer or supplier to determine the Arc flash suitability for the intended use.

Arc flash protective shirts should be thoroughly inspected before use to ensure no damage is present.

Specifications

Style:	Sky blue collared long sleeve shirt with reflective tape on sleeves.		
Fabric composition.			
rabric composition:	88% Cotton 12% Nylon.		
Mass:	237gsm/7oz.		
Reflective:	50mm Silver flame retardant tape.		
Additional:	Arc clothing must be worn with additional and		
	correctly selected Arc PPE to ensure complete		
	protection against the hazards of Arc Flash.		
	Refer to table "Arc Flash PPE Categories" for further		
	compatible PPE.		

Packaging, Storage & Obsolescence

DW-ARC9.6-S is packed in a polybag and sold individually.

Inspect all Arc PPE prior to use and do not use garments that are damaged (such as tears or burn holes) or dirty as the level of protection may be reduced.

The level of protection may also be reduced if you do not carefully follow the wash care instructions on the label.

If exposed to an Arc Flash incident, the garment must be replaced immediately.

Sizes Available

Small - 5XL

Size designation	1/2 Chest	Back length	Long sleeve length
S	53	75	63.5
М	58	77	64
L	63	79	65
XL	68	81	66
2XL	73	83	67
3XL	78	85	68
4XL	83	87	69
5XL	88	89	70

Dromex: Unit 1, 1 Blase Road, New Germany, 3620, South Africa T. +27(31) 713 1960 E. info@dromex.co.za www.dromex.co.za

Disclaimer Latest update: 02/06/2022 Dromex reserves the right to make changes without further notice to any products herein to improve function, design or reliability and validity. Dromex does not assume any liability arising out of the application or use of any product described herein. Reproduction in whole or in part is prohibited without the prior written consent of the copyright towner.


Compliance & Conformity

- Complies to marking SANS 724, Personal Protective Equipment and protective clothing against the thermal hazards of an electric Arc.
- IEC 61482-1-1- Live working Protective clothing against the thermal hazards of an electric Arc - Open Arc Test Method. It determines the Arc Thermal Protection Value (ATPV level) of the garment. The basic principle is that the ATPV of the garment must be higher than the Arc Flash energy.
- IEC 61482-1-2, Live working Protective clothing against the thermal hazards of an electric Arc - Box Test Method. It determines the Arc Protection Class Rating of the material or garment by using a constrained and directed Arc:
- EN 61482-1-2:2014 LIVE WORKING PROTECTIVE CLOTHING AGAINST THE THERMAL HAZARDS OF AN ELECTRIC ARC
- PART 1-2: TEST METHODS
- METHOD 2: DETERMINATION OF ARC PROTECTION CLASS OF MATERIAL AND CLOTHING BY USING A CONSTRAINED AND DIRECTED ARC (BOX TEST) (IEC 61482-1-2:2014).
- NFPA 2112 Standard on flame resistant clothing for protection of industrial personnel against short duration thermal exposures from fire.
- NFPA 70E Standard for electrical safety clothing for employees.
- ASTM F1959, Standard Test Method for Determining the Arc Rating of Materials for Clothing.
- ASTM F2621-12, Standard Practice for Determining Response Characteristics and Design Integrity of Arc Rated Finished Products in an Electric Arc Exposure.
- EN 11611:2015, Protective clothing for use in welding and allied processes.
- EN 11612:2015 Protective clothing -- Clothing to protect against heat and flame -- Minimum performance requirements.

Cleaning & Maintenance

Dromex[®] A.P.T[™] Garments can be cleaned by home or commercial laundry or by dry cleaning procedures without loss of their inherent protective features. The following suggestions will help keep your garment safe and neat. Should home procedures not remove contaminants, commercial laundering or dry-cleaning is recommended:

- Launder garments of Dromex[®] A.P.T[™] separate from personal non-flame resistant clothing to help avoid contamination by flammable materials.
- Pre-treat greasy stains and collar/cuff lines.
- Wash garments in warm water with heavy duty detergent.
- Do not use chlorine bleach or detergents containing chlorine bleach.
- Chlorine bleach may cause fading and reduce fabric strength.
- Tumble dry garments at a low setting.
- Remove and hang garments as soon as tumbler stops.
- Do not hang in direct sunlight as fading may occur.
- · When using commercial laundry aids, be sure to carefully follow the manufacturer's instructions.



Disposal

All industrial waste should be disposed of correctly according to local regulations and good disposal practice. Please consider recycling.

Marking

TYVEK ATPV LOOP FOLD CARE LABEL



ATPV 9,6 cal/cm²



Position: Shirt - Neck (Inside)

POCKET SIDEWINDER LABEL



Position: Shirt - Left chest pocket

DROMEX ARC BOOKLET



Position: Tag attached inside garment

SIZE LABEL

<- -12mm- -

Position:

 Shirt - Neck (Inside) **ORIGIN & YOM LABEL**

> MADE IN SOUTH AFRICA Y O M 2022

Position:

Shirt - Neck (Inside)



not overload home laundry equipment

Tumble dry garments at a low setting. Use the cool down cycle if available. Remove and hang garments as soon as tumble dryer stops. Do not hang in direct sunlight as it can cause fading and reduce fabric strength.

When using commercial laundry aids, be sure to read and carefully follow the manufacturer's instruction

Position:

EMBROIDERY (WHITE THREAD)



-Right hand side of chest






Position: All over print (Inside fabric)

Dromex: Unit 1, 1 Blase Road, New Germany, 3620, South Africa T. +27(31) 713 1960 E. info@dromex.co.za www.dromex.co.za

Latest update: 02/06/2022 Dromex reserves the right to make changes without further notice to any products herein to improve function, design or reliability and validity. Dromex does not assume any liability arising out of the application or use of any product described herein. Reproduction in whole or in part is prohibited without the prior written consent of the copyright owner

Shirt - Side seam (Above hem)





















ATV 9,0 Cal/Cm This garment is made of Dromex A.P.T™ (Arc Protective Technologies) and is a trademark of Dromex. Manufactured by Dromex P.O. Box 2005, New Germany, 3620 Tel: 031 713 1960. Fax: 031 705 6508 pose of this amment is to nortect andi The purpose of this garment is to protect against the thermal hazards created by an Arc Flash.

This garment is not suitable for fire fighting or any other posures where flame is of a continuous nature

Flammable contaminants will reduce the thermal protection of any flame-resistant garment. Wash the garment frequently to ensure that no greases, oi soils and other flammable contaminants are present when the garment is worn. Repairs to the garment must be made with flame resistant components.

RECOMMENDATIONS

To maximise protection, garments should be:

Loose fitting.
 Worn with flame resistant undergarments.
 Only made of cotton, silk or wool.
 To maximize comfort, silk or wool.

To maximise comfort: • Try on garments to check for correct fit before washing. Wash new garments before wearing to remov processing aids or finishes

For electric ARC exposure wear the correct number of flame ant clothing layers as dictated by an electric arc ha

resistant clothing layers as dictated by an electric arc hazard analyst. In potentially explosive environments, proper grounding procedures must be used for protection against electrostatic spark ignition. Do not put on or remove garments when in a potentially explosive environment.

Garments of Dromex A.P.T ™ brand fibre can be cleaned by home Garmens of uromexAk1 — brand more can be cleaned by home or commercial laundry or by dy cleaning procedures without affecting the lifespan of the garment or its protective features. The following suggestions will help keep your garment looking neat, attractive and safe. If home procedures do not remove contaminants, commercial laundering or dry cleaning is

Launder garments of Dromex A.P.T ™ separate from personal non-flammable materials. Pre-treat greasy stains and collar/cuff

Wash Garments in hot water with a heavy duty detergent. Do

Do not use chlorine bleach or detergents containing chlorine bleach as it may cause fading and reduce fabric strength

<---->





Position: Shirt - Above pocket

Disclaimer

Arc Flash PPE Categories



T. +27(31) 713 1960 E. info@dromex.co.za

www.dromex.co.za

Latest update: 02/06/2022 Disclaimer Dromex reserves the right to make changes without further notice to any products herein to improve function, design or reliability and validity. Dromex does not assume any liability arising out of the application or use of any product described herein. Reproduction in whole or in part is prohibited without the prior written consent of the copyright owner.